
Canal Seepage Loss in the Lower Beaverhead River Basin

Ground Water Investigation Program



Ginette Abdo

Montana Bureau of Mines and Geology

Glenn Shaw Montana Tech, Univ. of Montana



Ground Water Investigation Program (GWIP) Montana Bureau of Mines and Geology

- Specific groundwater research questions
- Local
- Sub-basin
- Very intensive, one to three year duration

Results

- A scientific basis for decision making and resource management
- Computer Model files passed on to other users
- A comprehensive set of hydrogeologic data available to the public

Today's Talk

Illustrate the importance of canal seepage in recharging groundwater which ultimately contributes to river base flow.

- Introduce the study area
- Mechanisms that result in groundwater recharge
- Groundwater hydrographs
- Seepage estimates on two canals
- Overall long-term influence of the East Bench Canal
- Monitoring results (seasonal) near both the East Bench and West Side Canals

Project Purpose

Is groundwater drawdown and stream depletion occurring due to high-capacity irrigation pumping from aquifers?

Main Project Objectives


- Groundwater movement and groundwater trends
- Water budget
- Quantify groundwater recharge from canals and irrigated fields
- Groundwater/surface-water interaction
- Evaluate potential stream depletion





Groundwater Recharge


East Bench Canal



Precipitation Influence



Departure from Annual Average Precipitation



Groundwater Trends

West Bench
Irrigation/Canal Seepage
Influence



PPpq PMsrm **KJTtkd** Tv Beaverhead Rock Ts Tv Dillon 2 Miles 0 Qal

Canal Monitoring Locations


Average seepage loss



West Side Canal1.2 cfs/mile

East Bench Canal2.2 cfs/mile


East Bench










Departure from Annual Average Precipitation












West Side Canal








Groundwater Recharge from Irrigation and Canal Seepage 2010

Seepage Loss 5,900 ac-ft/yr

Seepage Loss 17,000 ac-ft/yr



Average Canal Seepage Loses across Montana



- East Bench Canal
- West Side Canal
- Bozeman area ditches
- Upper Big Hole
- Helena Valley
- Billings area
- Stillwater-Rosebud Watershed
- Greenfields Bench

- 2.2 cfs/mile
- 1.2 cfs/mile
- 1.1 cfs/mile
- 0.15-1.5 cfs/mile
- 0.6 cfs/mile
- 0.05-0.5 cfs/mile
- 1.1-1.8 cfs/mile
- 0.45-4.7 cfs/mile

Factors influencing canal seepage

- Geologic material
- Depth to groundwater
- Irrigation season changes
- Wetted perimeter
- Maintenance





Factors influencing canal seepage

- Geologic material
- Depth to groundwater
- Irrigation season changes
- Wetted perimeter
- Maintenance



